BOREWELL CERTIFICATE

Name of the Work: Drilling of Bore wells providing pump motor and servicing at Kalastinagara ward No 15 Dasarahalli Sub Division

Job No: 015-14-000001

Work order No: EE/DD/WO/303/13-14 Date 26-02-14

BR No: 326/14-15 DATE 16.7.2014

The Inspection team deployed for this purpose has opined that generally the work executed is satisfactory (in the report available in the file. As such, compliance of Geological survey report, Yield test report and water probability tests report at this stage is not feasible, since this v k was executed _____ year's back.

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike